

**PROJECT ESTIMATE**

DATE: 11/05/2019

QUOTE ID: 4603
AR CUSTOMER: CMI MANAGEMENT (#10343)
SERVICE LOCATION: US ARMY RESERVE - CMI
STREET: 5363 PERU STREET, ROUTE 9
CITY: PLATTSBURGH, NY 12901

CONTACT: RON VOGT - CELL
Ph:(315) 772-8801
Fax:(315) 772-6336
steve.miller@cmimgmt.com

DATE SUBMITTED: 11/05/2019
PREPARED BY: FRASHER, LINDA

DESCRIPTION: Sensor

SCOPE OF WORK: CSS22280

We were asked to check a boiler - Alarm Code P2 Failure. Our technician determined that your PVI Boiler, Model # 126 EWB 125A-E, Serial # 1015140487 will need a new TP2 Sensor. The pricing shown below covers labor and materials required to do this work as well as TIME SPENT on November 4. Please call me at extension #236 if you have any questions. Thank you.

EQUIPMENT: M#:126 EWB 125A-E, S#: 1015140487, BOILER, Loc: PART#235828-1 / RIVERSIDE ELECTRIC BOILER, Eq#: 14492

ITEM	QUANTITY	UNIT PRICE	TOTAL
Labor Regular Time	4	\$110.00	\$440.00
Sensor and Plug	1	\$150.00	\$150.00
Environmental Fee	1	\$12.00	\$12.00
TIME SPENT on November 4 (\$50.00 - Vehicle, \$275.00 - Labor)	1	\$325.00	\$325.00
Total			\$927.00

SIGNATURE

PRINT NAME

DATE

**PROJECT ESTIMATE**

DATE: 11/05/2019

All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any alteration or deviation from the above specifications involving extra costs will be executed only upon written orders, and will become an extra charge over and above the estimate.

All agreements contingent upon strikes, accidents or delays beyond our control. Our technicians are covered by New York State Workers Compensation Insurance.

QUOTE VALID FOR THIRTY (30) DAYS