

PM-AN-10468

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

2 OVENS

ACTIVITY AND BLDG #: NY060 MAIN BLDG

LOCATION/RM #: Kitchen WO# 1708 ASSET # 10468

MECHANIC  
SIGNATURE:

Dave Rappel

DATE: 1-9-2019

START TIME:

FINISH TIME:

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
1	Notify cafeteria operator and get permission prior to performing all maintenance.	X		
2	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered.	X		
3	De-energize, lock out, and tag electrical circuits and fuel service.	X		
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Check with operating or area personnel for any deficiencies; verify cleaning program.	X		
2	Check all controls, mechanisms for proper operation; adjust as required.	X		
3	Examine utility supply line, piping, valve packing, specialties, and insulation; look for leaks.	X		
4	Check electric power line condition, switch, disconnect, etc.; or check condition of gas supply, valves, regulators, and inspect pilot, check for Gas leaks.	X		
5	Check the operation of thermostats; calibrate if required	X		
6	Clean and adjust gas burners.	X		
7	Check safety pilot and solenoid.	X		
8	Clean and adjust pilot light assembly.	X		
9	Check flue for proper draft or obstructions.	X	X	no flue
10	Lubricate gas valves.	X		
11	Clean interior walls and elements to obtain maximum heat transfer.	X		
12	Check gaskets and seals; check doors for tightness and warping; lubricate hinges and repair as necessary.	X		
13	Examine handles, knobs and controls for tightness and safe condition.	X		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes:

This checklist, 1 asset #, 2 ovens, top and bottom