

Argent Inspections

Form AI-03

Boiler Inspection Report

Inspection Date 10/1/2019	Certificate Issued Yes	Expiration Date	Prepared for Inspection Yes	Next Watersides/Firesides 2020/2020	Next Strength Test 0
Inspection Type(s) Performed <input checked="" type="checkbox"/> Internal <input type="checkbox"/> Watersides <input checked="" type="checkbox"/> Firesides <input checked="" type="checkbox"/> External/Operational <input checked="" type="checkbox"/> Pressure Test <input type="checkbox"/> Strength <input checked="" type="checkbox"/> Tightness					
Customer USARC Staten Island NY024			Boiler Location Name and/or Building Number Bldg 208		
Address 356 Battery Rd			Boiler Location Address		
City Staten Island	State NY	Zip 10305	City	State	Zip 0
National Board # 13036	Jurisdiction # Asset# 9648	Property # #2	Boiler Use Closed Heating Loop	Fuel Type Natural Gas	
Manufacturer Triad		Model # GPS-900-SH		Serial # 58056	Year Built 2012
Capacity 900,000 BTU/HR	Design Pressure 120 psi	Operating Pressure 12-20 psi	Programmer Manufacturer Honeywell	Burner Manufacturer Power Flame	
Number of Safety Valves 1	Combustion Efficiency % CO2 ppm CO % Excess O2				Flue Gas Temperature Degrees F
Valve 1	Valve Manufacturer Watts	Size 3/4"	Set Pressure 50 psi	Capacity 950,000 BTU/HR	Lift Pressure Hand
Valve 2					Reseat Pressure Sat
Valve 3:					
Valve 4:					
Safety Devices Tested Internal Flame Scanner, Low Gas Pressure Switch, High Gas Pressure Switch, Low Water Level Control (Electrically), Combustion Air Switch, Operating Temperature Control, High Temperature Lockout, Remote Emergency Disconnect. The safety valve was lifted by hand per NBIC Part 2 Sec 2.5.7.e. It lifted freely and reseated with no leakage.					
Reason(s) for Declining Certification					
Comments This Hot Water Heating Boiler was inspected per UFC 3-430-07, ASME CSD-1, and the National Board Inspection Code. Firesides were viewed and found to be in good condition with no signs of impingement, blistering or bagging. Watersides are required to be inspected every third year per UFC 3-430-07 Table 3-1. You should prepare to perform this inspection during the 2020 inspection.					
Inspector Commission 13314	Inspector Craig H. Bennett	Signature <i>Craig Bennett</i>			
Attachments No	Technical Manager Jerry Kuykendall	Signature <i>Jerry Kuykendall</i>			