

## Additional Funding Request

<b>Site: WV009</b>	<b>WO# 6861</b>	<b>CSS # 16473</b>	<b>Asset# NA</b>
Description of Repairs	Repair high hanging heater in the wash bay.		
Diagnosis: Initial Work Order <b>CSS# 17069</b>	Repair high hanging heater in the wash bay.		
Explanation of Additional Costs for Repairs	Investment is labor and lift rental to inspect issues with gas heaters in the Wash Bay located at USARC Clarksburg, WV009, CSS# 16473. If repairs are needed another quote will follow.		
Additional Labor Cost to Perform Repairs	Mechanic- 8 x \$115= \$920.00 Apprentice- 8 x \$93= \$744.00		
Additional Material Cost to Perform Repairs	\$280.50		
Total Cost of Repair	\$1,944.50		



## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV009 AMSA 102-G Date of Visit: 12/14/18  
269 ARMORY RD.  
CLARKSBURG, WV. 26301

Contractor Personnel on Site:

1. Steve Tregear 2. \_\_\_\_\_

### Work Performed:

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 155249

### Service Calls – Service Call Number and Description

1. CSS# 16473  
2. CSS# \_\_\_\_\_  
3. CSS# \_\_\_\_\_

---

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Steve Tregear Date: 12/14/18  
Signed: ST

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: John E. Casy Date: 14 DEC 18  
Signed: JEC  
E-Mail: John.E.Casy@DOD.mil