

Richard Hicks

From: Richard Hicks
Sent: Monday, January 4, 2021 11:23 AM
To: Richard Hicks

Tech Notes

Tech: BRIAN SCHAMP, Date: 11/4/20 8:30 AM - BRIAN SCHAMP. Site Start - 11/4/2020 8:30 AM
- ON SITE CHECKED IN WITH CHRIS. FOUND BROKEN MOTOR BRACKET AND ASSEMBLY ON WSHP#13. WILL QUOTE REPAIRS.
Site start 6:30AM
Picked up parts, arrived on site and located WSHP. Disassembled old motor bracket and put in new one. Started up unit and unit is back up and running
Paul Markham 12/9/20 tight up motor and checked motor opp
Paul Markham 12/10/20 got motor and unit back on line and checked opp and working order of unit unit is working great

Labor

| Date | Technician | Description | Hours |
|------------|---------------|------------------------|-------|
| 11/4/2020 | BRIAN SCHAMP | REGULAR HVACR LABOR | 1.00 |
| 11/4/2020 | BRIAN SCHAMP | COMMERCIAL TRAVEL TIME | 1.50 |
| 12/7/2020 | BRYAN MUSANTE | REGULAR HVACR LABOR | 8.00 |
| 12/9/2020 | PAUL MARKHAM | REGULAR HVACR LABOR | 1.00 |
| 12/10/2020 | PAUL MARKHAM | REGULAR HVACR LABOR | 2.00 |

Materials

| Date | Part Number | Description | Quantity |
|------------|----------------------------|--|----------|
| 11/4/2020 | CMISCX-TRUCK CHARGE | TRUCK CHARGE | 1.000 |
| 11/16/2020 | CMISCX-QUOTED GS AMOUNT | QUOTED AMOUNT SUBMITTED FOR THIS GENERAL SERVICE JOB | 13.500 |
| 11/16/2020 | CMISCX-TRIP CHARGE | TRIP CHARGE | 1.000 |
| 11/23/2020 | CMISCX-NON-STOCK ITEM | CLIMATE MASTER MOTOR | 1.000 |
| 11/23/2020 | CMISCX-FREIGHT-GS (NO TAX) | FREIGHT | 1.000 |
| 11/23/2020 | TAX-S | Sales Tax for Service | 1.000 |

| Signed By | | Signature | | Date | |
|-----------|--|-----------|--|------|--|
| | | | | | |

Rick Hicks
Project Manager Region 5
CMI Management Inc.
5285 Shawnee Road Suite #510
Alexandria, VA 22312
703-738-5301
Richard.Hicks@cmimgmt.com