



# PROPOSAL - CONTRACT

CMI Management  
Mr. Joe Bayne  
5285 Shawnee Rd.  
Alexandria, VA. 22312

March 3, 2020

RE: Saug NY128 css228565 WO  
6489  
DOMESTIC HOTWATER TANK #1  
IS LEAKING AT WATER FEED  
LINE

- Isolate compromised fitting.
- Remove fitting (s) as necessary and replace.
- Remove and re-install existing pipe insulation.
- check for leaks.

1 Misc copper fittings and solder	50.00
-----------------------------------	-------

sub total	50.00
-----------	-------

8hrs @120.00.	960.00
---------------	--------

sub total.	1010.00
------------	---------

20% profit/OH.	202.00
----------------	--------

Total.	1212.00
--------	---------

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email [rdpostulka@verizon.net](mailto:rdpostulka@verizon.net)

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL