



INVOICE

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

April 8, 2020

RE: Saug NY128 CSS#23294
Faucet

- Replace failed faucet assembly.
- Remove and re-install sink from wall
- Remove and replace broken drain trap assembly

1 K-59 Faucet assembly
1 PVC trap assembly

Total. 1100.56

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL