



PROPOSAL - CONTRACT

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

January 13, 2020

RE: Saug NY128 CSS#23294
Faucet

- Replace failed faucet assembly.
- Remove and re-install sink from wall
- Remove and replace broken drain trap assembly

1 K-59 Faucet assembly	221.00	221.00
1 PVC trap assembly	38.00	38.00

	sub total	259.00
	7% tax.	18.13

		277.13
	8hrs @80.00.	640.00

	sub total.	917.13
	20% profit/OH.	183.43

	Total.	1100.56

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL